



» Solve equipment problems

» Maximize performance

» Improve accuracy and increase productivity

# Ideal for a Wide Range of Applications: Ball Screws, Conveyor belts, X-Y Tables and more...

# **Compact!**

A super-compact, high-performance servo system that's easy to use.



## Smaller servo drives for multi-axis applications


The super-compact R7-Series is now even smaller. The footprint has been reduced by 52% from previous models minimizing control panel size.



# Easy!

## Real time autotuning sets the optimum gain.

An auto-tuning function calculates the device load in real time and automatically sets the optimum gain to simplify the adjustment procedure.



#### Installation


The Servo Drive can be mounted onto a DIN Rail by using the DIN Rail Mounting Unit (sold separately) for easier assembly and easier maintenance.



# Integrated development environment reduces your total cost of ownership.

The Servo system can be managed from design to maintenance with the CX-One Automation Suite.






# **Advanced functionality!**

# **Adaptive vibration suppression**

The resonant frequency is automatically monitored to remove vibration using the adaptive filter. Even if the resonant frequency changes due to low mechanical rigidity, real time evaluation automatically follows the changes to reduce the effect of vibration.




Reducing the amount of vibration improves positioning time and accuracy.



# Reduced process cycle time


The R7- Series accepts command pulse frequencies up to 500 kpps enabling high-speed positioning and high-precision control.





# **Closed loop system**

The present position can be checked using the feedback pulse sent from the Servo Drive to the Controller, allowing positioning errors due to mechanical problems to be monitored and eliminated in the Controller.




Simplified Synchronization: It is also possible to input encoder output signals directly into the servo drive.

# **Torque limiting function**

Set two torque limits, and switch between them. Great for application, such as pressing or part insertion.

Torque limiting reduces machine or work piece breakdown occurrence.




# **Interpreting Model Numbers**

## OMRON

# **Servo Drive Model Numbers**


The model number provides information such as the Servo Drive type, the applicable Servomotor capacity, and the power supply voltage.



## **Servomotor Model Numbers**

S2: With key tap

The model number provides information such as the Servomotor type, Servomotor capacity, rated speed and options.



# Servo Drive-Servomotor Combinations

Only the Servomotor and Servo Drive combinations listed here can be used. Do not use other combinations.

# **Cylindrical Servomotor**

**Servomotors Combinations** 

Voltage	Servo Drive	Servomotor		
Vollage	Pulse-train input	Rated output	Without brake	With brake
0	R7D-BPA5L	50 W	R88M-G05030H-S2	R88M-G05030H-BS2
Single-phase 120VAC	R7D-BP01L	100 W	R88M-G10030L-S2	R88M-G10030L-BS2
	R7D-BP02L	200 W	R88M-G20030L-S2	R88M-G 20030L-BS2
	R7D-BP01H	50 W	R88M-G05030H-S2	R88M-G05030H-BS2
Single-phase		100 W	R88M-G10030H-S2	R88M-G10030H-BS2
240 VAC	R7D-BP02HH	200 W	R88M-G20030H-S2	R88M-G20030H-BS2
	R7D-BP04H	400 W	R88M-G40030H-S2	R88M-G40030H-BS2
	R7D-BP01H	50 W	R88M-G05030H-S2	R88M-G05030H-BS2
Three-phase	K/D-BPUIN	100 W	R88M-G10030H-S2	R88M-G10030H-BS2
240 VAC	R7D-BP02H	200 W	R88M-G20030H-S2	R88M-G20030H-BS2
	R7D-BP04H	400 W	R88M-G40030H-S2	R88M-G40030H-BS2

#### Flat Servomotor

Servomotors Combinations

V-la	Servo Drive	Servomotor		
Voltage	Pulse-train input	Rated output	Without brake	With brake
Single-phase	R7D-BP01L	100 W	R88M-GP10030L-S2	R88M-GP10030L-BS2
120VAC	R7D-BP02L	200 W	R88M-GP20030L-S2	R88M-GP20030L-BS2
Single-phase 240 VAC	R7D-BP01H	100 W	R88M-GP10030H-S2	R88M-GP10030H-BS2
	R7D-BP02HH	200 W	R88M-GP20030H-S2	R88M-GP20030H-BS2
	R7D-BP04H	400 W	R88M-GP40030H-S2	R88M-GP40030H-BS2
	R7D-BP01H	100 W	R88M-GP10030H-S2	R88M-GP10030H-BS2
Three-phase 240 VAC	R7D-BP02H	200 W	R88M-GP20030H-S2	R88M-GP20030H-BS2
	R7D-BP04H	400 W	R88M-GP40030H-S2	R88M-GP40030H-BS2



### **Accessories and Cables**

#### CN1 Control Cables for CP1H/CP1L or general purpose controllers

Specifications		Model
Connector-Terminal Block Cables	1 m	XW2Z-100J-B28
Connector-Terminal Block Cables	2 m	XW2Z-200J-B28
General-purpose Control Cables	1 m	R7A-CPB001S
General-purpose Control Cables	2 m	R7A-CPB002S

#### Encoder Cables (for CN2) \*1

Specifications		Model
	3 m	R88A-CRGB003C
Standard Cables (connectors attached)	5 m	R88A-CRGB005C
	10 m	R88A-CRGB010C
	15 m	R88A-CRGB015C
	20 m	R88A-CRGB020C

#### Servomotor Power Cables (for CNB) \*1

Specifications		Model
	3 m	R7A-CAB003S
Standard Cables (connectors attached)	5 m	R7A-CAB005S
	10 m	R7A-CAB010S
	15 m	R7A-CAB015S
	20 m	R7A-CAB020S

#### **Brake Cables**

Specifications		Model
	3 m	R88A-CAGA003B
	5 m	R88A-CAGA005B
Standard Cables	10 m	R88A-CAGA010B
	15 m	R88A-CAGA015B
	20 m	R88A-CAGA020B

#### Connectors

Specifications	Model
Main Circuit Connector (CNA)	R7A-CNB01P
Servomotor Connector (CNB)	R7A-CNB01A
Control Input Connector (CN1)	R88A-CNW01C
Encoder Input Connector (CN2)	R88A-CNW01R
Servomotor Connector for Encoder Cable	R88A-CNG02R
Servomotor Connector for Servomotor Power Cable	R88A-CNG01A

#### Power Supply Cables (For CNA)

Specifications		Model
Power Supply Input Cable for Single-Phase Power (connectors attached)	2 m	R7A-CLB002S2
Power Supply Input Cable for Three-Phase Power (connectors attached)	2 m	R7A-CLB002S3
External Regenerative Resistor Connection Cable	2 m	R7A-CLB002RG

#### **Personal Computer Monitor Cable**

Specifications		Model
Personal Computer Monitor Cable	2 m	R88A-CCG002P2

<sup>\*1:</sup> For high flex cables add an "R" at the end of the part number.

#### Terminal Blocks for CP1H/CP1L or general purpose controllers

Specifications	Model
With M3 screws	XW2B-34G4
With M3.5 screws	XW2B-34G5
With M3 screws	XW2D-34G6

#### **External Regeneration Resistors**

Specifications	Model
220 W, 47 Ω	R88A-RR22047S
80 W, 100 Ω	R88A-RR080100S
80 W, 50 Ω	R88A-RR08050S

#### Reactors

Specifications	Applicable Servo Drive	Model
	R7D-BPA5L	3G3AX-DL2002
Single-phase 120 V	R7D-BP01L	3G3AX-DL2004
	R7D-BP02L	3G3AX-DL2007
	R7D-BP01H	3G3AX-DL2004
Single-phase 240 V	R7D-BP02HH	3G3AX-DL2004
	R7D-BP04H	3G3AX-DL2007
	R7D-BP01H	3G3AX-AL2025
Three-phase 240 V	R7D-BP02H	3G3AX-AL2025
	R7D-BP04H	3G3AX-AL2025


#### **DIN Rail Mounting Unit**

Specifications	Model
DIN Rail Mounting Unit	R7A-DIN01B

#### **Parameter Unit**

Specifications	Model
Parameter Unit	R88A-PR02G

#### **Servo Drive Nomenclature**



# Servo Terminal block (Relay Units) and Cables



Select the Servo Terminal block and Cable according to the model number of the Position Control Unit being used.

Position Control Unit	Position Control Unit Cable	Servo Terminal block (Relay Unit)	Servo Drive Cable'1	
CJ1W-NC133	XW2Z-050J-A18 XW2Z-100J-A18	XW2B-20J6-1B		
CJ1W-NC233	XW2Z-050J-A19	XW2B-40J6-2B		
CJ1W-NC433	XW2Z-100J-A19	XW2D-4030-2D		
CS1W-NC133	XW2Z-050J-A10 XW2Z-100J-A10	XW2B-20J6-1B		
CS1W-NC233	XW2Z-050J-A11	XW2B-40J6-2B		
CS1W-NC433	XW2Z-100J-A11	XW2B-40J0-2B		
CJ1W-NC113	XW2Z-050J-A14 XW2Z-100J-A14	XW2B-20J6-1B	XW2Z-100J-B29 XW2Z-200J-B29	
CJ1W-NC213	XW2Z-050J-A15	XW2B-40J6-2B		
CJ1W-NC413	XW2Z-100J-A15	XW2B-4030-2B		
CS1W-NC113	XW2Z-050J-A6	XW2B-20J6-1B		
C200HW-NC113	XW2Z-100J-A6	AW2B-2030-1B		
CS1W-NC213				
CS1W-NC413	XW2Z-050J-A7	XW2B-40J6-2B		
C200HW-NC213	XW2Z-100J-A7			
C200HW-NC413				
CJ1M-CPU21				
CJ1M-CPU22	XW2Z-050J-A33 XW2Z-100J-A33	XW2B-20J6-8A XW2B-40J6-9A (for 2 axes)	XW2Z-100J-B32 XW2Z-200J-B32	
CJ1M-CPU23	1000 7000	ATTER TOOLSA (IOI 2 axes)	XII 22 2000-102	
CQM1H-PLB21	XW2Z-050J-A3 XW2Z-100J-A3	XW2B-20J6-3B	XW2Z-100J-B29 XW2Z-200J-B29	

Note: 1. Two Servo Drive Cables are required if 2-axis control is performed.

Note: Cable Length

050 = 0.5 m 100 = 1 m 200 = 2 m

#### Characteristics

#### 120 VAC specification

Item	Servo Drive model			
nem	R7D-BPA5L	R7D-BP01L	R7D-BP02L	
Continuous output current (rms)	1.0 A	1.6 A	2.5 A	
Momentary maximum output current (rms)	3.3 A	5.1 A	7.5 A	
Power supply capacity	0.16 KVA	0.25 KVA	0.42 KVA	
Input power supply voltage (main circuit)	Single-phase 120 VAC (85 to 127 V), 50/60 Hz			
Input power supply current (rms) (main circuit)	1.4 A	2.2 A	3.7 A	
Heat generated (main circuit)	12 W	16 W	22 W	
Control method	All-digital servo			
Inverter method	IGBT-driven PWM method			
PWM frequency	12 kHz 6 kHz			
Maximum response frequency (command pulses)	Line drive: 500 kpps, Open collector: 200 kpps			
Weight	0.35 kg 0.42 kg			
Applicable motor capacity	50 W	100 W	200 W	

#### 240 VAC specification

240 VAC specification					
ltem	Servo Drive model				
nem	R7D-BP01H	R7D-BP02HH	R7D-BP02H	R7D-BP04H	
Continuous output current (rms)	1.0 A	1.6 A	1.6 A	2.5 A	
Momentary maximum output current (rms)	3.3 A	4.9 A	4.9 A	7.8 A	
Power supply capacity	0.27 KVA (0.30 KVA) See note	(0.35 KVA) See note	0.42 KVA	0.69 KVA (0.77 KVA) See note	
Input power supply voltage (main circuit)	Both single-phase and three-phase 200 to 240 VAC (170 to 264 V), 50/60 Hz				
Input power supply current (rms) (main circuit)	0.7 A (1.5 A) See note	(1.6 A) See note	1.1 A	1.8 A (3.5 A) See note	
Heat generated (main circuit)	14 W	16 W	20 W	26W	
Control method	All-digital servo				
Inverter method	IGBT-driven PWM method				
PWM frequency	12 kHz 6 kHz				
Maximum response frequency (command pulses)	Line drive: 500 kpps, Open collector: 200 kpps				
Weight	0.35 kg 0.42 kg			2 kg	
Applicable motor capacity	100 W	200 W	200 W	400 W	



#### 3,000-r/min Cylindrical Servomotors

#### 120 VAC specification

ltem	Unit	R88M-G05030H-S2	R88M-G10030L-S2	R88M-G20030L-52
Rated output '1	W	50	100	200
Rated torque'1	N⋅m	0.16	0.32	0.64
Rated rotation speed	r/min	3000		
Max. rotation speed	r/min	5000		
Max. momentary torque'1	N⋅m	0.48	0.95	1.78
Rated current '1	A (rms)	1.1	1.7	2.5
Max. momentary current '1	A (rms)	3.4	5.1	7.6
Rotor inertia	kg⋅m²	2.5 × 10 <sup>-6</sup>	5.1 × 10 <sup>-6</sup>	1.4 × 10 <sup>-5</sup>
Applicable load inertia		30 times rotor inertia max.		

<sup>\*1.</sup> These are the values when the Servomotor is combined with a Servo Drive at room temperature. The momentary maximum torque shown above indicates the standard value.

#### 3,000-r/min Cylindrical Servomotors

#### 240 VAC specification

Item	Unit	R88M-G05030H-S2	R88M-G10030H-S2	R88M-G20030H-S2	R88M-G40030H-52
Rated output'1	W	50	100	200	400
Rated torque'1	N⋅m	0.16	0.32	0.64	1.3
Rated rotation speed	r/min	3000			
Max. rotation speed	r/min	5000			
Max. momentary torque'1	N⋅m	0.48	0.95	1.78	3.60
Rated current*1	A (rms)	1.1	1.1	1.6	2.6
Max. momentary current '1	A (rms)	3.4	3.4	4.9	7.9
Rotor inertia	kg·m²	2.5×10 <sup>-6</sup>	5.1×10-6	1.4×10 <sup>-5</sup>	2.6×10 -5
Applicable load inertia		30 times rotor inertia max.			

<sup>\* 1.</sup> These are the values when the Servomotor is combined with a Servo Drive at room temperature. The momentary maximum torque shown above indicates the standard value.

#### 3,000-r/min Flat Servomotors

#### 120 VAC specification

İtem	Unit	R88M-GP10030L-S2	R88M-GP20030L-52	
Rated output 1	W	100	200	
Rated torque <sup>1</sup>	N⋅m	0.32	0.64	
Rated rotation speed	r/min	3000		
Max. rotation speed	r/min	5000		
Max. momentary torque'	N⋅m	0.85	1.86	
Rated current '1	A (rms)	1.6	2.5	
Max. momentary current '1	A (0-p)	6.9	10.5	
Rotor inertia	kg⋅m²	9.0×10 <sup>-6</sup>	3.4×10 <sup>-5</sup>	
Applicable load inertia		20 times rotor inertia max.		

These are the values when the Servomotor is combined with a Servo Drive at room temperature.
 The momentary maximum torque shown above indicates the standard value.

#### 3,000-r/min Flat Servomotors

#### 240 VAC specification

ltem	Unit	R88M-GP10030H-S2	R88M-GP20030H-S2	R88M-GP40030H-52
Rated output 1	W	100	200	400
Rated torque <sup>1</sup>	N⋅m	0.32	0.64	1.3
Rated rotation speed	r/min	3000		
Max. rotation speed	r/min	5000		
Max. momentary torque <sup>*1</sup>	N⋅m	0.90	1.82	3.60
Rated current '1	A (rms)	1.0	1.6	4.4
Max. momentary current '1	A (0-p)	4.3	6.8	18.6
Rotor inertia	kg⋅m²	9.0 × 10 <sup>-6</sup>	3.4 × 10 <sup>-5</sup>	6.4 × 10 <sup>-5</sup>
Applicable load inertia		20 times rotor inertia max.		

<sup>\*1.</sup> These are the values when the Servomotor is combined with a Servo Drive at room temperature. The momentary maximum torque shown above indicates the standard value.



OMRON ELECTRONICS LLC • THE AMERICAS HEADQUARTERS • Schaumburg, IL USA • 847.843.7900 • 800.556.6766 • www.omron247.com

OMRON CANADA, INC. • HEAD OFFICE

Toronto, ON, Canada • 416.286.6465 • 866.986.6766 www.omron247.com

OMRON ELETRÔNICA DO BRASIL LTDA • HEAD OFFICE

São Paulo, SP, Brasil • 55.11.2101.6300 • www.omron.com.br

OMRON ELECTRONICS MEXICO SA DE CV • HEAD OFFICE

Apodaca, N.L. • 52.811.156.99.10 • 001.800.556.6766 • mela@omron.com

**OMRON ARGENTINA • SALES OFFICE** 

Cono Sur • 54.11.4783.5300

OMRON CHILE • SALES OFFICE Santiago • 56.9.9917.3920

OTHER OMRON LATIN AMERICA SALES

54.11.4783.5300

OMRON EUROPE B.V. Wegalaan 67-69, NL-2132 JD, Hoofddorp, The Netherlands. Tel: +31 (0) 23 568 13 00 Fax: +31 (0) 23 568 13 88 www.industrial.omron.eu

Authorized Distributor:

#### Automation Systems

- $\bullet$  Programmable logic controllers (PLC)  $\bullet$  Human machine interfaces (HMI)  $\bullet$  Remote I/O
- Industrial PC's Software

#### Motion & Drives

• Motion controllers • Servo systems • AC drives

#### **Control Components**

- Temperature controllers Power supplies Timers Counters Programmable relays
- Digital panel indicators Electromechanical relays Monitoring products Solid-state relays
- $\bullet$  Limit switches  $\, \bullet$  Pushbutton switches  $\, \bullet$  Low voltage switch gear

#### Sensing & Safety

- Photoelectric sensors Inductive sensors Capacitive & pressure sensors
- Cable connectors Displacement & width-measuring sensors Vision systems
- Safety networks Safety sensors Safety units/relay units Safety door/guard lock switches

Note: Specifications are subject to change.

© 2011 Omron Electronics LLC

Printed in U.S.A.