Product data sheet Characteristics

VW3A9312

substitution kit for ATV38/58 - compatible with ATV61/ATV71

Adaptation accessories
Adaptor
Substitution kit for Altivar 38/58 drives
ATV61HD37N4HD75N4 ATV61HD37YHD90Y ATV71HD18M3XHD37M3X ATV71HD37N4HD75N4 ATV71HD37YHD90Y
Variable speed drive
Altivar 61 Altivar 71
Substitution of an ATV38HD46N4X by an ATV61HD37N4 Substitution of an ATV38HD54N4X by an ATV61HD45N4 Substitution of an ATV38HD64N4X by an ATV61HD55N4 Substitution of an ATV38HD79N4X by an ATV61HD75N4 Substitution of ATV58HD28M2XHD46M2X by ATV71HD22M3XHD37M3X Substitution of an ATV58HD28M2X by an ATV71HD18M3X Substitution of an ATV58HD33M2X by an ATV71HD22M3X Substitution of ATV58HD33N4HD79N4 by ATV71HD37YHD90Y Substitution of ATV58HD33N4HD79N4 by ATV71HD37YHD90Y Substitution of ATV58HD54N4HD79N4 by ATV71HD37N4HD55N4 Substitution of ATV58HD54N4HD79N4 by ATV71HD45N4HD75N4 Substitution of ATV58HD54N4HD79N4 by ATV71HD45N4HD75N4 Substitution of an ATV38HD46N4 by an ATV61HD37N4 Substitution of an ATV38HD54N4 by an ATV61HD45N4 Substitution of an ATV38HD64N4 by an ATV61HD45N4

Environment

RoHS EUR status	Compliant
RoHS EUR conformity date	1016

