

UNCONTROLLED DOCUMENT




PART NUMBER

SSA-LLP39793-5

REV.

NOTES:

1. WHITE POLYCARBONATE HOLDER.
2. LIGHT PIPES, MATERIAL CLEAR POLYCARBONATE. 8 PCS.
3. TOP SURFACE OF PIPES DIFFUSED.
4. LUMEX NAME AND PART NUMBER 40755-009 TO BE LOCATED ON TOP SURFACE.
5. POSTIONS 6, 7, 8 NO LIGHT PIPE.



*TOLERANCES PER DECIMAL PRECISION ARE: X=±1 (±0.039), X,X=±0.5 (±0.020), X,XX=±0.25 (±0.010), X,XXX=±0.127 (±0.005). LEAD LENGTH=±0.75 (±0.030). MIN.= +DECIMAL PRECISION MAX.= +0.00 -DECIMAL PRECISION

UNCONTROLLED DOCUMENT

REV.	PART NUMBER SSA-LLP39793-5	CONFIDENTIAL INFORMATION THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.	LUMEX INCORPORATED	290 E. HELLEN ROAD PALATINE, ILLINOIS 60067 PHONE: (847) 359-2790 WEB: http://www.lumex.com
5 UNIT LIGHT PIPE WITH REFLECTOR HOUSING.		RELIABILITY NOTE OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.	DRAWN BY: SS/BC	CHECKED BY: APPROVED BY: DATE: 3-22-00
			PAGE: 1 OF 1	SCALE: N/A